

## Photos of the Totland Landslide, December 2012

March 2013: The following photo of the Totland seawall was taken by the Coastguard in Spring 2013. It shows how far out the seawall was pushed following the landslide in late December 2012. The length of seawall affected was approximately 120 metres.



Photo: IOW Coastguard.

January 2014: The following photos show damage to the seawall, taken in December 2013 (IW Council):



